






For more information, please visit [novita.com.sg/NP200](http://novita.com.sg/NP200)

- DO NOT connect the unit to instantaneous water heater.
- Water may leak from the faucet attachment cap. Excessive load or pressure exerted may also damage the cap.
- Spout is covered with a plastic insulation cap. Excessive load or dramatical due to premature filter clogging.
- Change the filter or not fitted water correctly/surgically.
- Spout may be damaged or not attached correctly.
- If water leaks from the faucet attachment, the unit or faucet

#### NOTE




#### ⚠ Incompatible Faucet Type



Ensure a compatible faucet  
adapter is used.  
Non-standard  
adapter is available only  
upon request  
and subject to availability.  
to availability.

#### • Mounting Adapter



COMPATIBLE WITH MOST TYPES OF STANDARD FAUCET  
Standard mounting adapters are provided inside the product packaging box.

SIMPLE DIY INSTALLATION

15mm

25mm  
mm

D-type

22mm  
mm

B-type

19mm  
mm

C-type

17.5mm  
mm

A-type

Use the dimension below  
to check whether your  
faucet fits